


APPENDIX 16 Quick Fix Funding Bid Reference No:

1. Local Housing Office:	Manager: Paula Solowij
2. Location of works	Next to 132 Parliament Street.
3. Description of work(s)	Demolish Drying area.
4. Why is the work needed?	The drying area is not used and suffers from continued vandalism and fly tipping.
5. External proof of the ASB issues eg Police reports	Damage to gate and weekly dumping of rubbish.
6. Proof of consultation	Letters sent to 24 residents with SAE's for reply. 14 residents responded all in favour.
7. Actual take up and number of properties benefiting. (Include numbers of tenants and leaseholders/owner occupiers)	Approx 20 properties. Majority returned.
8. Costs (quotes, SORs etc)	

9. Map and photo of area and any other information e.g. planning



Map Centered at OS Grid ref: SK342356, Easting: 434269, Northing: 335607, Lat: 52.916°, Long: -1.490°.

Drying area near 132 Parliament Street.

